

## Roof – Scope of Work




#### Scope of Work

- Replace shingled roof portion of the home with standing seem metal roof that is black or charcoal in color
- Metal roof to be supplied from McElroy Metal (supplemental brochure with detailed specs attached)
  - 1500 Hamilton Road Bossier City, LA 71111

#### **Metal Panel Roof Details**

- System: 238T -OR- Maxima 2"
- Panel Height: 2.375" / 2" mechanically seamed
- Panel Width: 16"
- Configuration: Striated, Plank, Flat or Minor Rib
- Color family: Black/ Charcoal/ Slate
- Cut sheets shown on page 5; full brochure included as separate attachment

## Roof – Detailed Measurements



#### **Detailed Measurements**

• Surface Area: 3,403.04 ft

Total Perimeter Length: 339.89 ft

Number of Squares: 34.03 ft

• Total Ridge Length: 69.70 ft

# Roof – Primary Concern





#### Concern

 Various portions of the roof have a pitch of less than 2:12 rendering shingled roof unwarrantable by the manufacturer and out of NC Building Code



### Roof – Cut Sheets





## Gutters – Scope of Work



#### Scope of Work

- Terminate internal gutter system and replace with 6"-7" seamless box-style gutters
- New gutters to be either aluminum or copper
- If aluminum, color to match color of roof (black/ charcoal/ slate)
- Box style gutters are being chosen since they will most closely replicate the look of the existing internal gutters



## Gutters – Primary Concerns: Leaking and Improper Drainage



Water penetration through office windows in rear of home



Improperly sloped gutters resulting in overflowing, erosion and wood rot

#### Concerns

- Existing gutters have been improperly maintained over the years
- Existing gutters are too shallow to accommodate for proper drainage during heavy rains
- These factors have led to drainage issues, wood rot and leaking in the house


# Gutters – Primary Concerns: Leaking and Improper Drainage



Water penetration through ceiling of lower level in rear of home



Water pooling in lower level by office



Water pooling in lower level

## Gutters – Proposed Solution



#### Rationale

- Most closely replicates the look of the existing internal gutters and will be nearly indistinguishable from the original internal gutters when viewing from the street
- Superior performance relative to existing gutters
- 6"-7" size being chosen to accommodate for reduction in height of fascia board of existing gutters (8") once ~2" of tar and gravel roof is removed





# Madison Ave: Street View 1 – Existing Roof





# Madison Ave: Street View 1 – Proposed Roof





# Madison Ave: Street View 2 – Existing Roof





# Madison Ave: Street View 2 – Proposed Roof





# Madison Ave: Street View 3 – Existing Roof





# Madison Ave: Street View 3 – Proposed Roof





## Clifton Street: Street View 4 – Roof Not Visible From Clifton Street



Vantage Point

